



Tips To Enhance

The Candle-Making Process



Use a wick that matches the candle's size to avoid sooting.



Avoid adding essential oil in the midst of heating the wax.



Add the color dye when the wax is hot to achieve an even spread.



Use slow movements to mix the wax to keep it from frosting.



A heat gun can help smoothen out the candle's bumps and cracks.



Poke holes into the candle to keep air pockets at bay.

